

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

《DIAGNOSIS COMMENT WITH RESPECT TO
SLIDE BEARING PORTION》

- OVERHAUL TIMING : O/O/O
- FAILURE MODE : FATIGUE WEAR
- FAILURE REASON: VIBRATION AND OVERLOAD

⋮